

33/01/01 B
- from MetSkers

33/01/01 B
- from MetSkers

WATER WELL REPORT

STATE OF WASHINGTON

Application No.

Permit No.

(1) OWNER: Name L K. Ferguson Address 421 McClaine Silverton OR.
 (2) LOCATION OF WELL: County # Island sec # 7 1/4 Sec 16 T. 33 N. R. 1 E W.M.
 Bearing and distance from section or subdivision corner Park Access Records # 7650-00-0000-26 LOT # 26

(3) PROPOSED USE: Domestic ☒ Industrial ☐ Municipal ☐
 Irrigation ☐ Test Well ☐ Other ☐

(4) TYPE OF WORK: Owner's number of well (if more than one) _____
 New well ☒ Method: Dug ☐ Bored ☐
 Deepened ☐ Cable ☒ Driven ☐
 Reconditioned ☐ Rotary ☐ Jetted ☐

(5) DIMENSIONS: Diameter of well 6" inches.
 Drilled 228 ft. Depth of completed well 228 ft.

(6) CONSTRUCTION DETAILS:
 Casing installed: 6" Diam. from 0' ft. to 218' ft.
 Threaded ☐ 5" Diam. from 223 ft. to 228 ft.
 Welded ☒ Diam. from _____ ft. to _____ ft.

Perforations: Yes ☐ No ☒
 Type of perforator used _____
 SIZE of perforations _____ in. by _____ in.
 _____ perforations from _____ ft. to _____ ft.
 _____ perforations from _____ ft. to _____ ft.
 _____ perforations from _____ ft. to _____ ft.

Screens: Yes ☒ No ☐ Johnson
 Manufacturer's Name _____
 Type _____ Model No. _____
 Diam. 6" Slot size 25 from 218 ft. to 223 ft.
 Diam. _____ Slot size _____ from _____ ft. to _____ ft.

Gravel packed: Yes ☐ No ☒ Size of gravel: _____
 Gravel placed from _____ ft. to _____ ft.

Surface seal: Yes ☒ No ☐ To what depth? 19+ ft.
 Material used in seal: clay
 Did any strata contain unusable water? Yes ☐ No ☒
 Type of water? _____ Depth of strata _____
 Method of sealing strata off _____

(7) PUMP: Manufacturer's Name _____
 Type: _____ H.P. _____

(8) WATER LEVELS: Land-surface elevation 291 ft.
 Static level 211 ft. below top of well Date July 85
 Artesian pressure _____ lbs. per square inch Date _____
 Artesian water is controlled by _____ (Cap, valve, etc.)

(9) WELL TESTS: Drawdown is amount water level is lowered below static level
 Was a pump test made? Yes ☐ No ☒ If yes, by whom? _____
 Yield: _____ gal./min. with _____ ft. drawdown after _____ hrs

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test _____
 Baller test: 2 gal./min. with 0 ft. drawdown after 1 1/2 hrs.
 Artesian flow: _____ g.p.m. Date _____
 Temperature of water: _____ Was a chemical analysis made? Yes ☐ No ☐

(10) WELL LOG:

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of formation.

MATERIAL	FROM	TO
0'-3' TOP SOIL	0'	3'
HARD PAN GRAY in color	3'	44'
Clay with sand GRAY in color	44'	91'
Sand with some clay LIGHT GRAY	91'	166'
Sand with small Rock BROWN	166'	183'
CORSE sand with small Rock + clay	183'	195'
HARD PAN GRAY	195'	218'
Sand + small Rock	218'	223'
clay GRAY in color	223'	228'

well will yield more than
 8 G.P.M. This is the only test
 that I could make accurately

(needs to be pump tested)

Work started July, 1985 Completed July, 1985

WELL DRILLER'S STATEMENT:

This well was drilled under my jurisdiction and this report is true to the best of my knowledge and belief.

NAME BedRock Well Drillers
 (Person, firm, or corporation) (Type or print)

Address 150 W TRAXELL R.d. Oak Harbor WA 98277

[Signed] Scott Statton
 (Well Driller)

License No. 1368 Date 1-20- 1986